

# GM CETC BEDFORD FACILITY BEDFORD, INDIANA

RCRA CORRECTIVE ACTION/CERCLA REMOVAL ACTION

GM CETC BEDFORD FACILITY, BEDFORD, INDIANA

# Welcome to the 3nd Quarter 2010 Public Information Session September 30, 2010



- Facility located on 152.5 acres and is approximately 1,000,000 square feet of manufacturing footprint
  - Approximately 400 employees




# REMOVAL ACTION

RCRA CORRECTIVE ACTION/CERCLA REMOVAL ACTION

- Comprehensive Environmental Response,
   Compensation, and Liability Act (CERCLA) Removal Action (RA)
  - Bailey's Branch and Pleasant Run PCB cleanup of creek sediments and floodplain soil.
  - RA Elements:
    - Control of impacted springs and seeps along creeks; and
    - Removal of floodplain soil to 1.8 ppm and sediment to 1 ppm in the creek.
  - GM LLC and MLC completed an agreement to consolidate the remaining creek removal work with the work at the East Plant Area.
    - GM LLC completed additional soil transportation in August/September 2010 from Peerless Road stockpile;
    - Restoration of excavated areas will continue into 2011.



RCRA CORRECTIVE ACTION/CERCLA REMOVAL ACTION





#### REMOVAL ACTION STATUS

CORRECTIVE ACTION/CERCLA REMOVAL ACTION

**DIVERSION CHANNEL NO. 3** 


**NEW RESTORATION BETWEEN BROOMSAGE ROAD AND PEERLESS ROAD** 

**EAST PLANT AREA VAULT** 

**PARCEL 400 AREA** 

**WEST PLANT AREA** 

PARCEL 201



**STAGING AREA G** 

**RESTORATION SOUTH OF BROOMSAGE ROAD** 

RESTORATION **EAST OF BAILEY SCALES ROAD** 

RESTORATION **WEST OF BAILEY SCALES ROAD** 



RCRA CORRECTIVE ACTION/CERCLA REMOVAL ACTION

GM CETC BEDFORD FACILITY, BEDFORD, INDIANA

West from Bailey Scales Road





RCRA CORRECTIVE ACTION/CERCLA REMOVAL ACTION

GM CETC BEDFORD FACILITY, BEDFORD, INDIANA

#### East from Bailey Scales Road









RCRA CORRECTIVE ACTION/CERCLA REMOVAL ACTION

GM CETC BEDFORD FACILITY. BEDFORD. INDIANA




South of Broomsage Road Restoration



RCRA CORRECTIVE ACTION/CERCLA REMOVAL ACTION

GM CETC BEDFORD FACILITY. BEDFORD. INDIANA




Looking south from Broomsage Road



RCRA CORRECTIVE ACTION/CERCLA REMOVAL ACTION

GM CETC BEDFORD FACILITY. BEDFORD. INDIANA



Restoration North of Broomsage Road



RCRA CORRECTIVE ACTION/CERCLA REMOVAL ACTION

GM CETC BEDFORD FACILITY, BEDFORD, INDIANA



Looking north of Broomsage Road restoration

-09/29/2010



RCRA CORRECTIVE ACTION/CERCLA REMOVAL ACTION

GM CETC BEDFORD FACILITY, BEDFORD, INDIANA









Looking north of Broomsage Road restoration



# CREEK RESTORATION STATUS

RCRA CORRECTIVE ACTION/CERCLA REMOVAL ACTION

GM CETC BEDFORD FACILITY. BEDFORD. INDIANA



Restoration east of Peerless Road



RCRA CORRECTIVE ACTION/CERCLA REMOVAL ACTION

3 M CETC BEDFORD FACILITY, BEDFORD, INDIANA



**Restoration East of Peerless Road** 



# CREEK EXCAVATION STATUS

RCRA CORRECTIVE ACTION/CERCLA REMOVAL ACTION

GM CETC BEDFORD FACILITY, BEDFORD, INDIANA



Excavation and soil pile remaining west of Peerless Road



# CREEK EXCAVATION STATUS

RCRA CORRECTIVE ACTION/CERCLA REMOVAL ACTION

GM CETC BEDFORD FACILITY, BEDFORD, INDIANA




Soil pile remaining west of Peerless Road (September 2010)



RCRA CORRECTIVE ACTION/CERCLA REMOVAL ACTION

GM CETC BEDFORD FACILITY. BEDFORD. INDIANA




Naturalized excavation west of Peerless Road



# TRUCK TRAFFIC ROUTES

RCRA CORRECTIVE ACTION/CERCLA REMOVAL ACTION

- Increased road traffic will continue this fall, particularly along Peerless and Breckenridge Roads, as resumption of restoration work gets underway, and again next summer as the off-Site work is completed.
- CRA continuously monitors safety of truckers.
- GM completed paving a stretch of Peerless and Breckenridge Roads in response to resident concerns about road conditions.
- At the end of truck traffic, GM will be placing a final surface layer on the portions of road recently repaved.
- GM will be patching/paving roads as needed.
- Truck Traffic Issues:
   Katie Kamm (812) 277-8954





# **Typical Trucks**

- Soil Removal, Restoration and Cover System Construction Activities
  - Trucks transporting <50</li>
     ppm PCB soil for use in cover system construction at Plant.
  - Trucks transporting clean soil from off-Site locations for restoration.







#### RCRA CORRECTIVE ACTION

RCRA CORRECTIVE ACTION/CERCLA REMOVAL ACTION

GM CETC BEDFORD FACILITY, BEDFORD, INDIANA

#### RCRA Corrective Action

- Conducted under a performance-based agreement with the U.S. EPA Region V. The agreement was signed on March 20, 2001 and amended October 1, 2002, March 29, 2008, and May 9, 2008
- Groundwater testing completed in July/August 2010.
- Implementing Interim Measures
  - East Plant Area
  - West Plant Area



RCRA CORRECTIVE ACTION/CERCLA REMOVAL ACTION

GM CETC BEDFORD FACILITY, BEDFORD, INDIANA






RCRA CORRECTIVE ACTION/CERCLA REMOVAL ACTION

#### East Plant Area Interim Measure

- Re-use of creek soil
- Select soil removal/landfill vault
- Cover system
- Perimeter groundwater collection
   System
- AOI 8 collection system
- Long-term maintenance and monitoring
- Complete work areas
  - Current work areas
  - Paving planned for 2010
  - Planned for 2011





RCRA CORRECTIVE ACTION/CERCLA REMOVAL ACTION

GM CETC BEDFORD FACILITY. BEDFORD. INDIANA



Parcel 201 off of GM Drive with completed cover.



RCRA CORRECTIVE ACTION/CERCLA REMOVAL ACTION

GM CETC BEDFORD FACILITY, BEDFORD, INDIANA



Completed cover area off of GM Drive. Small amount of grading seeding remains.



RCRA CORRECTIVE ACTION/CERCLA REMOVAL ACTION

GM CETC BEDFORD FACILITY. BEDFORD. INDIANA



Liner installed east of water treatment facility prior to clay grading.



RCRA CORRECTIVE ACTION/CERCLA REMOVAL ACTION

GM CETC BEDFORD FACILITY, BEDFORD, INDIANA



Erosion control matting on the completed cover across from the Plant.

- The drier than normal summer has caused some difficulty in growing new grass.
- Overseeding of problem areas is planned this fall.



RCRA CORRECTIVE ACTION/CERCLA REMOVAL ACTION

GM CETC BEDFORD FACILITY, BEDFORD, INDIANA



Partially completed covers and temporary liners visible around the stormwater pond.



RCRA CORRECTIVE ACTION/CERCLA REMOVAL ACTION



Stockpiling creek material in the East Plant Area off GM Drive.



RCRA CORRECTIVE ACTION/CERCLA REMOVAL ACTION

GM CETC BEDFORD FACILITY, BEDFORD, INDIANA

 The former excavation in front of the plant will have a permanent vegetative and asphalt cover placed over the former excavation.





# UPCOMING RCRA ACTIVITIES

RCRA CORRECTIVE ACTION/CERCLA REMOVAL ACTION

GM CETC BEDFORD FACILITY, BEDFORD, INDIANA

#### **UPCOMING ACTIVITIES FOR 2010**

- Continue East Plant Area Cover System
- Continue restoration east of Peerless Road
- Button down work areas in preparation for winter and spring rainy season
- Continue RFI groundwater monitoring
- Complete additional bedrock studies at AOI 8
- Complete design of Pilot Perimeter Groundwater Collection Trench
- Additional soil sampling beneath clean clay pad in Area G, west of Peerless Road
- Additional soil sampling in Parcel 400/430/431 area



# COMMUNITY RELATIONS ACTIVITIES

RCRA CORRECTIVE ACTION/CERCLA REMOVAL ACTION

GM CETC BEDFORD FACILITY, BEDFORD, INDIANA

- Community meetings are held on a quarterly basis.
  - Presentations have been and will continue to be posted to the website
  - People can always come to the field trailer and talk one-on-one or call Katie Kamm: (812) 277-8954
- Next meetings will be held in December 2010
- CLP Meeting to be held on October 1, 2010



# COMMUNITY RELATIONS ACTIVITIES

RCRA CORRECTIVE ACTION/CERCLA REMOVAL ACTION

- Project website at: http://www.BedfordPowertrainCorrectiveAction.com
- Quarterly Community Meetings are available on the website
- Public Information Repository (GM Plant) currently by appointment with Katie and repository publications are also available on the project website
- Community Liaison Panel (CLP) members listed in minutes on website
- Periodic information sessions
- Periodic Project Fact Sheets (twenty-seven issued to date)
- Project Questions or Truck Traffic Issues contact Katie Kamm: (812) 277-8954